Glenn Hoppin 919-733-6592 Division of Health Service Regulation TAX +o

PRINTED: 03/16/2015 FORM APPROVED

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION DENTIFICATION NUMBER-COMPLETED A. BUILDING; 01 B. WING 02/11/2015 FCL011193 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 101 COUNTRY TIME LANE EVERGREEN LIVING HOME #1 LEICESTER, NC 28748 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR L9C IDENTIFYING INFORMATION) PREFIX PREFIX COMPLETE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) (C 000) Initial Comments (C 000) Report by Glenn Hoppin CONSTRUCTION SECTION A Biennial Follow-up Survey was conducted on February 11, 2015 starting at 9:00AM and ending at 9:45AM. Not all of the previously cited MAR 3 0 2015 deficiencies were corrected. Therefore, further action is required. RECEIVED The remaining deficiencies that were observed are as follows: (C 115) Construction-Consult Local BI for Permits {C 115} SECTION .0300 - THE BUILDING 10A NCAC 13G .0302 DESIGN AND CONSTRUCTION The local code enforcement official shall be consulted before starting any construction or renovations for information on required permits and construction requirements. This Rule is not met as evidenced by: On the rear of the facility an outside utility building has been converted into an assembly hall. The building is being heated with 3 kerosene heaters and 5 gallons of kerosene was being stored in the building. The building has no smoke detectors or fire extinguishers. Also several dropcords were observed in the facility to power lights and the sound system. The utility building is less than 8 feet from the facility. The entry ramps into the building do not meet family care home rules or the North Carolina State Bullding Code, Cease using the building immediately and consult with the local building official, the local fire official and the DHSR Construction section to determine what Building had permit as a changes and improvements will be required to use the building as an assembly hall. Obtain all Storage Building necessary permits and submit copies of all Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE.

Administrator

Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION DENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING. FCL011193 02/11/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 101 COUNTRY TIME LANE **EVERGREEN LIVING HOME #1** LEICESTER, NC 28748 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE SUMMARY STATEMENT OF DEPICIENCIES (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PREFIX CROSS-REFERENCED TO THE APPROPRIATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION] TAG DEFICIENCY) (C 115) Continued From page 1 (C 115) permits, approvals, invoices, and any other supporting documentation to the DHSR Construction Section. 02/11/2015-GH- At the time of our survey a walk thru was conducted through the utility building, at this time we discovered that the kerosene heaters and kerosene storage cannisters had been removed, the issue with supports; integrety of the electrical wiring wall and ceiling finishes and building classification are still in question, we are awaiting a ruling from the local Building Official that this dwelling meets the minimum requirements as an Assembly Occupancy as clissified by the North Carolina State Building Code!

Division of Health Service Regulation STATE FORM

1FKS22

DO NOT REMOV	E FROM JOB SITE B BL 0 15 - 00 29 3
P	UNCOMBE COUNTY - INSPECTION REQUEST FORM Repro IR122001
Owner Name:	€ Phone Number:
Address of Inspection :	101 Country Time La
Contractor: Directions:	m R 100 Phone Number: 776 1030
Date Inspected: 0 3	17-15 Inspector KRP
Foundation I	ireplace/ firebox Plumbing Under Gas Piping Saw Service sulation Rough Plumbing Rough Mechanical Rough Electrical uilding Final Mechanical Final Electrical Final
Inspection Results: 🔲 App	roved Disapproved Is this a Reinspection? Ves No
Buldry as	lang 12 question has Been cleaned out of